

Brother HL-L2300D Toner Reset

The Brother HL-L2300D printer may report low toner when there is still toner left in the cartridge. This error will not always be resolved by replacing the toner. Complete the following steps to reset the toner counter.

1. **Press and Hold** the **Power** button until the machine turns off
2. **Open** the **Toner Door**
3. **Press and Hold** the **Go** button until **step 5**
4. **Press** the **Power** button
5. **Release** the **Go** button when the **Toner, Paper,** and **Drum** lights are lit
6. **Press** the **Go** button **9 times**
7. **Wait** for the **Toner, Paper,** and **Drum** lights to be lit
8. **Press** the **Go** button **5 times**
9. **Close** the **Toner Door**

Revision #3

Created 23 May 2019 16:00:09 by Joshua Prince

Updated 20 February 2020 20:13:22 by Joshua Prince